

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MDS-501

No. 416

Subject: Incorrect track assignment

Date: November 30, 1994

Symptom:

(**)

When making a digital recording from a CD, the MDS-501 may assign more tracks than originally on the Compact Disc.

Solution:

Replace IC210, which is on the digital board, with the improved version. The improved version is CXD-8495AQ, the part number is 8-759-294-79.



Filename: HFP0416.SB
Directory: J:\SBDOC\NOV94
Template: C:\WINWORD\S_BULL.DOT
Title: Incorrect track assignment
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 11/30/94 1:45 PM
Revision Number: 2
Last Saved On: 11/30/94 1:45 PM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 0 Minutes
Last Printed On: 04/01/96 10:04 AM
As of Last Complete Printing
Number of Pages: 2
Number of Words: 117 (approx.)
Number of Characters: 671 (approx.)