

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MDS-501

No. 422

Subject: Symptoms requiring MO focus bias adjustment

Date: December 27, 1994

Symptom:

(**)

On a recordable disc one or more of the following problems may occur:

- 1.) Recording is not possible.
- 2.) Sound will skip during Playback.
- 3.) "DISC ERROR" appears in the display
- 4.) "RETRY ERROR" appears in the display
- 5.) A disc cannot be ejected
- 6.) TOC information cannot be read.
- 7.) The unit will stop during playback.

Solution:

Re-adjust the MO FOCUS BIAS as outlined in the MDS-501 Supplement-1 Service Manual (P/N 9-959-262-82).



