

# Hi-Fi Products Service Bulletin

**CSA-13**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** RM-VP1

**No.** 425

**Subject:** Part Numbers Missing from Service Manual

**Date:** January 9, 1995

**Symptom:**

(\*\*)

The remote commander RM-VP1, used with the STRG1ES, has some part numbers missing from the Service Manual.

**Solution:** Add the following part numbers to your Service Manual.

REF	DESCRIPTION	PART NUMBER
IC4	S-8100B	8-759-194-49
CP1	SENSOR (ANGULAR VELOCITY)	1-810-423-11
CP2	SENSOR (ANGULAR VELOCITY)	1-810-423-21



