

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-X779ES

No. 432

Subject: Intermittant lock up of functions

Date: March 20, 1995

Symptom:

(12)

The unit will intermittantly not operate when using the front panel function buttons or the remote commander.

Solution: Replace IC801 with the part listed below.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
IC801	MSC62408-046GS-V1K	8-759-099-03	MSC62408-101GS-V1K	8-759-167-74



Filename: HFP0432.SB
Directory: J:\SBDOC\MAR95
Template: C:\WINWORD\S_BULL.DOT
Title: Replacement IC801
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 03/20/95 10:05 AM
Revision Number: 2
Last Saved On: 03/20/95 10:05 AM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 1 Minute
Last Printed On: 04/01/96 9:31 AM
As of Last Complete Printing
Number of Pages: 2
Number of Words: 124 (approx.)
Number of Characters: 708 (approx.)