

# Hi-Fi Products Service Bulletin

**CSA-13**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** TC-WR445

**No.** 457

**Subject:** Erratic Deck Operation

**Date:** November 10, 1995

**Symptom:**

(62)


Deck A operates erratically due to incomplete meshing of Gear (A/B) and trigger lever.

**Solution:**

Replace Gear (A/B) in the DC motor assy. See part numbers listed below.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
M2	GEAR (A/B)	3-918-330-01	GEAR (A/B)	3-918-330-02

Applicable Serial number range:- from 826023 and up.



Filename: HFP0457.SB  
Directory: J:\SBDOC\NOV95  
Template: C:\WINWORD\TEMPLATE\S\_BULL.DOT  
Title:  
Subject:  
Author: "tech pub"  
Keywords:  
Comments:  
Creation Date: 11/10/95 9:50 AM  
Revision Number: 2  
Last Saved On: 11/10/95 9:50 AM  
Last Saved By: Hoyt Wing Lee  
Total Editing Time: 0 Minutes  
Last Printed On: 04/01/96 10:16 AM  
As of Last Complete Printing  
Number of Pages: 1  
Number of Words: 127 (approx.)  
Number of Characters: 729 (approx.)