

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MDS-101, MDS-501, MDS-302, MDS-JA3ES

No. 478

Subject: Syncro Record Operation is Not Available
when connected to an MDP Player

Date: April 5, 1996

Symptom:

(**)

Unable to Syncro record when connected to an MDP Player. This is due to different SIRCS codes used in MDP Players and CD Players.

Solution:

Explain to customers that Syncro record can only be used with a Sony CD player. Recording from an MDP to minidisc can be done manually using the front panel buttons or by using the individual units remote commanders.

-

