

Sony Service Company  
National Technical Services  
A Division of Sony Electronics Inc.  
Park Ridge, New Jersey 07656

## Service Bulletin Hi-Fi Products

**Model:** MDS-S35, MDS-302, MDS-JA3ES

**No. 491**

**Subject:** Note when replacing Optical Block

**Date:** June 14, 1996

**Symptom:**

(\*\*\*\*)

There are several types of optical block assemblies and it is sometimes necessary to remove a mounted component when installing a new optical block assembly. In instances where component removal is required, a notice is packed with the replacement part outlining the specific component to remove. In addition to the component outlined in the notice remove the capacitor listed below.

**Solution:**

Remove the following capacitor when replacing the Optical Block assembly. Removing C168 produces no side effect.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
C168	0.1UF CERAMIC CHIP	1-163-038-91	REMOVE	N/A

