


Model: DXA-C70, DXA-H2750, DXA-H3750, HCD-541, **No. 526**
 HCD-551, HCD-C50, HCD-H61, HCD-H61M,
 HCD-H170, HCD-H650, HCD-D359, HTC-H2800,
 TC-H1600, TC-H1700, TC-H2600, TC-H3600,
 TC-H6600, TC-K461S, TC-K615S, TC-KE200,
 TC-KE300, TC-KE400S, TC-KE500S, TC-RX311,
 TC-RX370, TC-RX390, TC-TX1, TC-W320, TC-
 W370, TC-WE805S, TC-WR520, TC-WR535, TC-
 WR545, TC-WR565, TC-WR570, TC-WR590, TC-
 WR620, TC-WR635S, TC-WR645S, TC-WR665S,
 TC-WR670, TC-WR690, TC-WR720

Subject: New Part Number For Head Base Assembly **Date:** May 6, 1997

Symptom:
 (**) The original Base Assembly, Head p/n A-2003-757-A or A-2003-838-F has been replaced.

Solution: Use the following part numbers when ordering a replacement Head Base Assembly. Also replace the Torsion Spring when replacing the Head Base Assy.

REF	DESCRIPTION	PART NUMBER
N/A	BASE ASSY, HEAD	A-2004-527-A
N/A	SPRING, TORSION	3-907-362-01



Applicable Models:

Models using the TCM-190 tape mechanism.