



Sony Service Company
National Technical Services
A Division of Sony Electronics Inc.
Park Ridge, New Jersey 07656

CONFIDENTIAL

Service Bulletin

Hi-Fi Products

CSA-13

Model: CDP-CX90ES, CDP-CX270

No. 533

Subject: Digital Noise in Audio

Date: June 12, 1997

Symptom:

(54) The customer may complain of a "beep" noise on the audio.

Solution: Perform the following:

- 1.) Using a razor knife, cut the foil patterns outlined below.
- 2.) Connect jumper wire leads from A to B and from C to D (see diagram).

