

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** D-321**No.****Subject:** The Prevention Plate Comes Off When Battery Is  
Inserted backward**Date:** January 11, 1994**Symptom:****(\*\*)**

The prevention plate comes off when battery is inserted backward

**Solution:**

Replace the prevention plate with the following part indicated below.

REF	DESCRIPTION	PART NUMBER
60	PLATE, PREVENTION	4-961-288-02





## **Service Bulletin Check-Off Form**

Originator: ..... Cesar Bechbache

Diagram Location: .

<b>PERSON</b>	<b>ACTIVITY</b>	<b>INITIAL</b>	<b>DATE</b>	<b>COMMENTS</b>
Originator	Draft Creation			
Wing	Drawings & Numbering			
Originator	Proofing			
Manager	Approval			
	Notify KCP			
	AutoFlagging			
Wing	Distribution			
Rob	SDIS Entry			