

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

---

**Model:** MDS-101**No. 370****Subject:** Non-Sony Discs Jam During Loading, Or Load  
Slowly**Date:** January 24, 1994**Symptom:**  
**(65)**

In some units, discs which are not made by Sony may occasionally jam during loading, or may load slowly.

**Solution:**

If a unit is exhibiting this problem, install the parts kit shown below. The kit consists of an improved SHUTTER LEVER and TORSION SPRING.

REF	DESCRIPTION	PART NUMBER
-	LEVER (SHUTTER L) KIT	X-4944-745-1





## Service Bulletin Check-Off Form

Originator: ..... Larry Redner

Diagram Location: .

<b>PERSON</b>	<b>ACTIVITY</b>	<b>INITIAL</b>	<b>DATE</b>	<b>COMMENTS</b>
Originator	Draft Creation			
Wing	Drawings & Numbering			
Originator	Proofing			
Manager	Approval			
	Notify KCP			
	AutoFlagging			
Wing	Distribution			
Rob	SDIS Entry			