

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** D-121/125**No.****Subject:** CD Not Locking - Reconnect CN501**Date:** February 2, 1994**Symptom:**  
(12)

Unit would not read disc, indicating "No Disc" on display.

**Solution:** Reconnect connector CN501 onto Main Board.

| REF   | DESCRIPTION              | PART NUMBER  |
|-------|--------------------------|--------------|
| CN501 | CONNECTOR, FPC (ZIF) 18P | 1-566-534-11 |

Applicable serial numbers: 432240 and lower





## **Service Bulletin Check-Off Form**

Originator: ..... Cesar Bechbache

Diagram Location: .

| <b>PERSON</b> | <b>ACTIVITY</b>      | <b>INITIAL</b> | <b>DATE</b> | <b>COMMENTS</b> |
|---------------|----------------------|----------------|-------------|-----------------|
| Originator    | Draft Creation       |                |             |                 |
| Wing          | Drawings & Numbering |                |             |                 |
| Originator    | Proofing             |                |             |                 |
| Manager       | Approval             |                |             |                 |
|               | Notify KCP           |                |             |                 |
|               | AutoFlagging         |                |             |                 |
| Wing          | Distribution         |                |             |                 |
| Rob           | SDIS Entry           |                |             |                 |