

---

**Model:** CPD-100ES, CPD-200ES**No. 178****Subject:** Improved IC901 CPU on the D Board**Date:** February 5, 1998**Symptom:****(\*\*\*)**

If the CPU IC901 needs to be replaced on the D Board, an improved component is available for IC901 replacement. The new IC901 operating program provides improved DDC access timing.

**Solution:**

Then, please use the new description and part number given in the table below to order replacement parts. Update the schematic diagram and parts list references in the service manual for each respective model.

REF	DESCRIPTION	PART NUMBER
IC901	ST7272N5B1/CUS	8-749-014-36