

SONY®

Service Bulletin

NO: ME3-99-001

SUBJECT: MD MAY NOT LOAD/SHUTTER MAY NOT CLOSE WHEN DISC EJECTS

DATE: JANUARY 1999

MODEL (S): MDX-C670/C7900/C8900

SYMPTOM: The disc may not load during insertion. Also, the shutter may not close when the disc is being ejected. The mech. deck is the MG-164 series.

SOLUTION: Replace the Holder Assembly with an improved part.

REF	DESCRIPTION	PART NUMBER
106	HOLDER,ASSY(A)	X-3376-333-1

Applicable S/N: MDX-C670 up to 15467
MDX-C7900 up to 77700
MDX-C8900 up to 10000

Sony of Canada Ltd.

115 Gordon Baker Road, Toronto, Ontario M2H-3R6
NATIONAL LAB - CONSUMER SERVICE

SONAM 449
ME98015
ME02098