

SONY®

Service Bulletin

NO: ME3-99-006

SUBJECT: FRONT PANEL DOOR MAY OPEN

DATE: MARCH 1999

MODEL (S): MDX-62

Symptom: The Front Panel door may open by a slight mechanical shock. This may occur when driving. The lock is loose because the lock rib height is too low.

Solution: Replace the Front Panel with a new improved one.

DESCRIPTION	PART NUMBER
DOOR & FRONT PANEL ASSY	X-3376-77-1

Applicable Serial Numbers: 10001 to 19840
20341 to 20740

Sony of Canada Ltd.

115 Gordon Baker Road, Toronto, Ontario M2H-3R6
NATIONAL LAB - CONSUMER SERVICE

SONAM 463
ME98030