

Computer Monitors Service Bulletin

CSI-111

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: GDM17SE1, GDM20SE1

No. 86

Subject: D824 Improvement

Date: March 20, 1995

Symptom:


(131) No Picture due to HV shutdown

Solution: Please check D-824 on the D-Board. If shorted, replace as follows:

1. Replace D824 with a 1SS83 type

DESCRIPTION	PART NUMBER
1SS83 DIODE	8-719-901-83

2. Apply RTV to locations illustrated below:



Filename: C_P0086.SB
Directory: J:\SBDOC\MAR95
Template: C:\WINWORD\S_BULL.DOT
Title: CSI-111, D824 change GDM17se1
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 03/20/95 8:50 AM
Revision Number: 2
Last Saved On: 03/20/95 8:50 AM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 0 Minutes
Last Printed On: 04/01/96 9:31 AM
As of Last Complete Printing
Number of Pages: 2
Number of Words: 112 (approx.)
Number of Characters: 644 (approx.)