

Computer Monitors Service Bulletin

CSI-111

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: GDM17SE1, GDM20SE1

No. 74

Subject: Improved Part

Date: December 22, 1994

Symptom:

(**)

If D503, D505 and D506 require replacement, use the new replacement.

Solution: D503, D505 and D506 were changed to the following new part below:

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
D503	ERC91-02 DIODE	8-719-920-67	ERC90M-03 DIODE	8-719-048-73
D506	ERC91-02 DIODE	8-719-920-67	ERC90M-03 DIODE	8-719-048-73
D505	EGP30G DIODE	8-719-979-57	ERC90M-03 DIODE	8-719-048-73



