SONY

SERVICE MANUAL

AE-6D chassis

MODEL	COMMANDER	DEST	CHASSIS NO.	MODEL	COMMANDER	DEST	CHASSIS NO.
KD-32DX100U	RM-933	UK	SCC-Q84B-A	KD-32NX100U	RM-935	UK	SCC-Q84A-A
KD-32NS100B	RM-935	FR	SCC-Q85A-A				

CORRECTION - 1

SUBJECT : CHANGES TO SECTION 3 SET-UP ADJUSTMENTS


File this correction with the service manual




Corrected Item

SECTION 3-2. CONVERGENCESee page 22

HTIL Adjustment




HTIL correction can be performed by adding a TLH correction assembly to the Deflection yoke.






TLH Adjustment






TLH correction can be performed by adding a TLH correction assembly to the Deflection yoke.





Note: TLH piece should be used on one side only. Insert into either the left or right side of the DY as necessary.

Screen Corner Convergence

If you are unable to adjust the corner convergence properly, this can be corrected with the use of permalloy magnets.







If you are unable to adjust the corner convergence properly, this can be corrected with the use of permalloy magnets.

