

Warning for Firmware Upgrade of SGI/SGA/SFA Products

Firmware upgrade of the SGI/SGA/SFA products should only be performed using the latest version of the Flash Wizard utility, Version 1.12. Please **DELETE** any Flash Wizard executable files (FlashWizardSG.exe) which are Versions 1.11 or earlier.



CAUTION

Upgrading firmware using Flash Wizard Version 1.11 or earlier, could result in unintentional presence of voltage/current (up to full-scale in value) at the output terminals of the power supply during the upgrading procedure. This could present a shock hazard to the user if contact is made with the output terminals, or possibly damage the load circuitry connected to the power supply.

Note: This presence of full-scale voltage/current on the output terminals presents no detrimental effect to the power supply itself. Also, this hazard does not exist during normal operation of the SGI/SGA/SFA power supply after the firmware is upgraded, but only during the upgrading procedure.