



A-Pillar Lower Trim Panel Upgrade

Classification	Repair Bulletin	Section/Group	15 - Interior Trim	Country/Region	North America
Year	2012	Model	Model S	Version	All

Bulletin Classification: This repair bulletin provides instructions and guidelines for a noted condition or a customer concern. The information provided can address a broad range of known or perceived issues with the operation of Tesla vehicles. This bulletin might not be VIN-specific. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

This Service Bulletin supersedes SB-13-15-002 R1, dated 30-Jan-14. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

Condition

Upgraded A-Pillar lower trim panels are now available. These new panels are grained and fit better with the adjacent parts.

Correction

Upon customer complaint, replace the LH and RH A-pillar lower trim panels (Figure 1) with the upgraded parts.




Figure 1 (RH side shown)

Required Part(s):	Part Number	Description	Quantity
	1010668-00-D	ASY, A PILLAR TRIM LOWER LH	1
	1010669-00-D	ASY, A PILLAR TRIM LOWER RH	1
	1014969-00-A	TRIM CLIP, TRW 1030063840	As required

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Correction Description	Correction	Time
Vehicle Inspection Only, A-Pillar Lower Trim Panel Upgrade Not Required	S011315002	0.1
Replace LH And RH A-Pillar Lower Trim Panels	S021315002	0.3

Procedure

1. Replace the LH and RH A-Pillar lower trim panels with the upgraded parts (refer to Service Manual procedure 15180102).

Affected VIN(s) This information is for reference purposes only. This list is not intended to be the sole information source for updates.

5YJSA1DP8CFF00001 - 5YJSA1DP0CFF00042
 5YJSA1DP6CFP01201 - 5YJSA1DP5CFP01206
 5YJSA1AP7CFR00102 - 5YJSA1AP9CFR00117

For feedback on the accuracy of this document, email ServiceBulletinFeedback@teslamotors.com.