



## Driver's Footrest Upgrade

<b>Classification</b>	Repair Bulletin	<b>Section/Group</b>	15 - Interior Trim	<b>Country/Region</b>	North America
<b>Year</b>	2012	<b>Model</b>	Model S	<b>Version</b>	All

**Bulletin Classification:** This repair bulletin provides instructions and guidelines for a noted condition or a customer concern. The information provided can address a broad range of known or perceived issues with the operation of Tesla vehicles. This bulletin might not be VIN-specific. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

This Service Bulletin supersedes SB-13-15-004 R1, dated 30-Jan-14. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

### Condition

An upgraded driver's footrest is now available. The new part has a grained finish and features the Tesla logo.

### Correction

Upon customer complaint, replace the driver's footrest with the upgraded part.

Required Part(s):	Part Number	Description	Quantity
	6005968-00-C	FOOT REST, DRIVER	1

This part number was current at the time of publication. Use the revision listed or later, unless otherwise specified in the Parts Manual.

Correction Description	Correction	Time
Vehicle Inspection Only, Driver's Footrest Upgrade Not Required	S011315004	0.1
Replace Driver's Footrest	S021315004	0.2

### Procedure

1. Replace the driver's footrest with the upgraded part (refer to Service Manual procedure 15185002).

---

**Affected VIN(s)**

This information is for reference purposes only. This list is not intended to be the sole information source for updates.

5YJSA1DP8CFF00001 - 5YJSA1DP0CFF00042  
5YJSA1AP7CFR00102 - 5YJSA1AP9CFR00117  
5YJSA1DP6CFP01201 - 5YJSA1DP5CFP01254  
5YJSA1DP2CFS00001 - 5YJSA1DP4CFS00100

For feedback on the accuracy of this document, email [ServiceBulletinFeedback@teslamotors.com](mailto:ServiceBulletinFeedback@teslamotors.com).

