



Charge Port Door Upgrade

Classification	Campaign Bulletin	Section/Group	44 - High Voltage System	Country/Region	North America
Year	2014	Model	Model S	Version	All

Bulletin Classification: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electricity repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

Condition

Some vehicles were supplied with inadequate adhesive on the metal charge port door disk. If the disk separates from the charge port door, the charge port door stays open.

Correction

Replace the charge port door.

Required Part(s):	Part Number	Description	Quantity
	1007189-00-G	ASY - CHARGE PORT DOOR	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Correction Description	Correction	Time
Vehicle Inspection Only; Charge Port Door Replacement Not Required	S011444005	0.1
Replace Charge Port Door Due To Inadequate Adhesive	S021444005	0.4

Procedure

1. Replace the charge port door (refer to Service Manual procedure 44012302).

Affected VIN(s) Affected Model S vehicles built between approximately June 19, 2014 and June 30, 2014.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@teslamotors.com.