



## Retrofit Model S Fog Lamps

<b>Classification</b>	Campaign Bulletin	<b>Section/Group</b>	17 - Electrical	<b>Country/Region</b>	Canada, Europe
<b>Year</b>	2015	<b>Model</b>	Model S	<b>Version</b>	Premium Interior and Lighting Package

**Bulletin Classification:** *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

### Condition

Some Canadian and European Model S vehicles were built without front fog lamps despite being configured with the Premium Interior and Lighting package.

### Correction

Replace the front cornering lamps with fog lamps.

Required Part(s):	Part Number	Description	Quantity
	<b>Canada:</b>		
	6005913-00-F	LAMP ASY - FRT FOG/SD REFLEX - SAE (LH)	1
	6005914-00-F	LAMP ASY - FRT FOG/SD REFLEX - SAE (RH)	1
	<b>Europe:</b>		
	6005915-00-E	LAMP ASY - FRT FOG ECE (LH)	1
	6005916-00-E	LAMP ASY - FRT FOG ECE (RH)	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Correction Description	Correction	Time
SB-15-17-008 Not Applicable	S011517008	0.00
Vehicle Inspection Only; Fog Lamp Retrofit Not Required	S021517008	0.05
Retrofit Front Fog Lamps - Vehicles With Premium Interior and Lighting Package	S031517008	0.75

## Procedure

1. Inspect the front lower lamp assemblies for fog lamp lenses (Figure 1).
  - If the lower lamps already have fog lamp lenses, discontinue this procedure.
  - If the lower lamps do not have fog lamp lenses, continue this procedure.



**Figure 1 (Fog lamp lens highlighted)**

2. Remove the front cornering lamps and replace them with fog lamps (refer to Service Manual procedure 17404002).

**NOTE:** Update the vehicle configuration, as described in Service Manual procedure 17404002.

---

**Affected VIN(s)** Affected Canadian and European Model S vehicles that are configured with the Premium Interior and Lighting package and were built between approximately May 6, 2015 and July 28, 2015.

**NOTE:** This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email [ServiceBulletinFeedback@teslamotors.com](mailto:ServiceBulletinFeedback@teslamotors.com).