



Replace 2nd Row Center Seat Belt Due To Missing or Incorrect Label

Classification	Campaign Bulletin	Section/Group	20 - Safety and Restraint	Country/Region	Europe
Year	2014 - 2015	Model	Model S	Version	All

Bulletin Classification: *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

This Service Document supersedes SB-16-20-001, dated 12-Oct-16. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

Condition

On some European Model S vehicles, the 2nd row center seat belt has an incorrect or missing label. Passenger safety is not affected.

Correction

Replace the 2nd row seat center seat belt with one that has the correct label (Figure 1).



Figure 1 (Correct label on replaced part)

Correction Description	Correction	Time
SB-16-20-001 Not Applicable	S011620001	0.0
Replace 2 nd Row Center Seat Belt Due To Incorrect Or Missing Label	S021620001	0.2

Required Part(s):	Part Number	Description	Quantity
	1021792-00-B	EU - SEATBELT ASSY, 2ND ROW CTR BLK	1

This part number was current at the time of publication. Use the revision listed or later, unless otherwise specified in the Parts Manual.

Procedure

Replace the 2nd row center seat belt (refer to Service Manual procedure 20056302).

Affected VIN(s) Affected Model S vehicles built between approximately December 30, 2014 and June 22, 2015.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.