

Replace Continental 19" Tires Date Coded 1317

Classification Campaign Bulletin Section/Group 34 - Wheels & Country/Region United States

Tires

Year 2017 Model Model 3 Version All

Bulletin Classification: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

Condition

Certain Model 3 vehicles equipped with Continental 19" tires with a date code of 1317 might not conform to Tesla's subjective requirements for performance and customer satisfaction.

Correction

Replace Continental 19" tires date coded 1317.

Correction Description	Corre	ction Ti	ime
SB-17-34-001 Not Applicable	S0117	7 34001 0.	00
Inspect All Tires, No Replacement Necessary	S0217	7 34001 0.	05
Inspect All And Replace 1 Tire Date Coded 1317	S0317	7 34001 0.	35
Inspect All And Replace 2 Tires Date Coded 1317	S0417	7 34001 0.	65
Inspect All And Replace 3 Tires Date Coded 1317	S0517	7 34001 0.	95
Inspect All And Replace 4 Tires Date Coded 1317	S0617	7 34001 1.	25

Required Part(s): Part Number Description Quantity
1044255-00-A TIRE, 235/40R19 96W, CONTI A/S As Required

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Procedure

Inspect the date code of the front LH tire (Figure 1).



Figure 1 (date code circled in red)

- If the date code on the tire is 1317, go to step 2.
- If the date code on the tire is not 1317, go to step 6.
- Remove the tire and wheel from the vehicle (refer to Service Manual procedure 34015001).
- 3. Dismount the tire from the wheel, and mount the replacement tire onto the wheel (refer to Service Manual procedure 34021002).

NOTE: Make sure the date code of the replacement tire is not 1317.

- 4. Balance the tire and wheel (refer to Service Manual procedure 34022005).
- 5. Install the tire and wheel onto the vehicle (refer to Service Manual procedure 34015001).
- 6. Repeat step 1 through step 5 for the front RH tire, rear RH tire, and rear LH tire.

Affected VIN(s) A

Affected Model 3 vehicles built before approximately August 2, 2017.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.