



Replace Underhood Storage Area Child Safety Switch

Classification	Campaign Bulletin	Section/Group	15 - Interior Trim	Country/Region	United States
Year	2017	Model	Model 3	Version	All

Bulletin Classification: *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

Condition

An improved version of the Model 3 child safety switch in the underhood storage area now features a glow-in-the-dark button instead of a lighted button.

Correction

Replace the child safety switch with the updated part.

Correction Description	Correction	Time
Replace Child Safety Switch In Underhood Storage Unit	S011815001	0.05

Required Part(s):	Part Number	Description	Quantity
	1107722-00-D	M3 SWITCH FRT TRUNK CHILD SAFETY	1

This part number was current at the time of publication. Use the revision listed or later, unless otherwise specified in the Parts Manual.

Procedure

Replace the underhood storage area child safety switch (refer to Service Manual procedure 15241402).

Affected VIN(s) Affected Model 3 vehicles built before approximately November 7, 2017.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.