



Replace Charge Port Carrier Assembly For Seized Latch Actuator

Classification	Campaign Bulletin	Section/Group	44 - High Voltage System	Country/Region	United States, Canada
Year	2017 - 2019	Model	Model 3	Version	All

Bulletin Classification: *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

Condition

Certain Model 3 vehicles were manufactured with charge port carrier assemblies that do not meet Tesla's internal specifications, and the latch actuator within the assembly might seize. If the actuator seizes open, vehicle charging is affected. If the actuator seizes closed, insertion or removal of the charging handle is prevented.

Correction

Replace the charge port carrier assembly with an updated part.

Correction Description	Correction	Time
SB-19-44-007 Not Applicable	S011944007	0.00
Replace Charge Port Carrier Assembly	S021944007	0.65

Required Part(s):	Part Number	Description	Quantity
	1492302-10-B	LATCH SUB ASSY,SERVICE,CP,NA,M3	1
	1111033-00-E	M3 2R BOLSTER CLIP	1
	1117252-00-A	BOLT,HF,M12x40,STL[109],ZN,ADH,MAT	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Special Tool(s):	Part Number	Description
	1108272-00-B	CAP, LOGIC CONN, INV, 3DU
	1130480-00-A	TEST PROBES, SLIM, FLUKE TP38

Procedure

Replace the charge port carrier assembly (refer to Service Manual procedure 44012102).

Affected VIN(s) Affected Model 3 vehicles built between approximately November 27, 2017 and March 22, 2019.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.

