



Provide Type 2 Charging Cable

Classification	Repair Bulletin	Section/Group	50 - External Charging Connectors	Country/Region	EMEA
Year	2019	Model	Model S, Model X, Model 3	Version	All

Bulletin Classification: *This repair bulletin provides instructions and guidelines for a noted condition or a customer concern. The information provided can address a broad range of known or perceived issues with the operation of Tesla vehicles. This bulletin might not be VIN-specific. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

Condition

Some EMEA Model S, Model X, and Model 3 vehicles were delivered without a Type 2 charging cable.

Correction

Inspect the vehicle for the symptom related to the condition. If the symptom is present, provide a Type 2 charging cable to the customer.

Correction Description	Correction	Time
SB-19-50-003 Not Applicable	S011950003	0.00
Inspect Vehicle, Type 2 Charging Cable Already Present	S021950003	0.05
Inspect Vehicle, Provide Type 2 Charging Cable	S031950003	0.05

Required Part(s):	Part Number	Description	Quantity
		Use one of the following:	
	1039810-00-A or	EV CHARGING CABLE MODE 3, GEN 2, 3 PH	0-1
	1039810-01-A	EV CHARGING CABLE MODE 3, GEN 2, 3 PH	0-1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Procedure

Inspect the underhood storage unit and trunk:

- If a Type 2 charging cable (Figure 1) is found in the vehicle, discontinue this procedure and do not provide a new Type 2 charging cable to the customer.
- If a Type 2 charging cable is not found in the vehicle, provide a new Type 2 charging cable to the customer.



Figure 1

Affected VIN(s) Affected Model S, Model X, and Model 3 vehicles built between approximately January 1, 2019 and March 31, 2019.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.