

 Tesla, Inc. Service Bulletin		<h2><i>Replace RH Taillight Due To Color Mismatch</i></h2>	
SB-21-17-003 April 19, 2021			
Classification Repair Bulletin		Section/Group 17 - Electrical	Mobile Service Can Perform (where permitted)
Model Year 2021	Model Model Y	Country/Region North America	Version All
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Repair Bulletin: This repair bulletin provides instructions on addressing a noted condition or possible customer concern regarding the operation of Tesla vehicles. These instructions should only be performed by trained professionals.

Condition

On some Model Y vehicles, the color of the red band that surrounds the LH and RH taillights do not match because the vehicle has Revision D for the LH taillight (Figure 1) which has a darker tint, and the right side has Revision C (Figure 2) which has a lighter tint. This is only a cosmetic issue that does not affect the performance of the taillights.



✓ **Figure 1 – Revision D LH Taillight**



✗ **Figure 2 – Revision C RH Taillight**

Correction

Inspect the vehicle for a color mismatch of the taillights. If a color mismatch is present, replace the RH taillight with Revision D.

Correction Description	Correction	Time
Replace RH Taillight Due To Color Mismatch	S012117003	0.20

Part Number	Description	Quantity
Parts Required 1502087-00-D	LAMP ASY, REAR BODYSIDE, RH	1

Procedure

Replace the RH taillight (refer to Service Manual procedure [17402002](#)).