TESLA	Tesla, Inc. Service Bulletin		Replace the HV Battery		
SB-22-16-001 R1 March 4, 2022 R1					
Classification			Section/Group	Mobile Service	Configuration
Campaign Bulletin			16 - HV Battery System	Cannot Perform	Heat Pump
Model Y	Model		Country/Region	Build Location	
2021	Model Y,	Model 3	North America, Asia Pacific,	Giga Shanghai, Fremont	
			Europe		
	and model year(s) list f this bulletin for a part		al approximation of the affected VIN list. Refer t	o the VIN/Bulletin Tracker or Cus	tomer/Vehicle profile to determine

Campaign Bulletin: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN list.

This Service Bulletin supersedes SB-22-16-001, dated 14-Jan-22. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

Condition

On certain Model 3 and Model Y vehicles, the HV battery may not have been manufactured to internal specifications, potentially resulting in a reduction of range.

Correction

Replace the HV battery.

Correction Description	Correction	Time
SB-22-16-001 Not Applicable	S012216001	0.00
Replace the HV Battery	S022216001	4.30

	Part Number	Description	Quantity
Parts Required	1666969-00-C	LFP+ PACK 3PH	1
		North America, Japan and South Korea Only:	
	1666968-00-C	ASY,HVBAT,LFP60,RWD,1PH,M3	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the <u>Parts Catalog</u>.

Shop Supplies IPA wipes

Procedure

Replace the HV battery (refer to Service Manual procedure 16010102 Model 3, Model Y).