



APPROVED

ORIGINATED BY DAN DAWLINGTON MODEL OR MODULE AFFECTED M19H

NATURE AND REASON FOR CHANGE Dealing with th M19H
2 band oscillator in the Monitor Circuit
it has been found that the "Star" value resistor
(R47), that a great majority of the time that the Builders
562 resistors have had to be replaced w/ the 822 to correct
for band #3 high end flatness in this change would save
time for both the unit personnel & the initial technician.

DRAWING AFFECTED AND HOW (USE MARKER PRINTS AND ADDITIONAL SHEETS AS NEEDED)

ACTION			INITIALS	REASONS
PROJ. ENG.	APP	DISAPP		
MECH ENG.	APP	DISAPP		
OTHER	APP	DISAPP		
OTHER	APP	DISAPP		
CH. ENG.	 APP	DISAPP		
ECN#				