Technical Note

Battery Fuse Holders 512-0088-01-01 Rev 1

Incorrect Hardware Stack-Up On Fuse Holders

AFFECTED MODELS

НВ 200-Т	P/N 84-4155-00	includes clamp
НВ 300-Т	P/N 84-4156-00	includes clamp
М-НВ 200-Т	P/N 84-4158-00	
М-НВ 300-Т	P/N 84-4154-00	

We have encountered several occasions where the hardware has been stacked incorrectly during installation of these fuse holders. During these instances of incorrect hardware stack-up, the flat washer was placed between the fuse and the battery cable. This incorrect stack-up creates a highly resistive connection that generates heat. This can cause the fuse to overheat and blow open and partially melt the fuse holder and cover. If you have any questions concerning this bulletin or any other issues, please contact Xantrex.

Xantrex is a registered trademark of Xantrex International. © 2003 Xantrex International. All rights reserved.

Technical Note: Incorrect Stack-Up On Fuse Holders© January 1996 Xantrex International

UNLESS SPECIFICALLY AGREED TO IN WRITING, XANTREX TECHNOLOGY INC. ("XANTREX"):

(a) MAKES NO WARRANTY AS TO THE ACCURACY, SUFFICIENCY OR SUITABILITY OF ANY TECHNICAL OR OTHER INFORMATION PROVIDED IN ITS MANUALS OR OTHER DOCUMENTATION.

(b) ASSUMES NO RESPONSIBILITY OR LIABILITY FOR LOSS OR DAMAGE, WHETHER DIRECT, INDIRECT, CONSEQUENTIAL OR INCIDENTAL, WHICH MIGHT ARISE OUT OF THE USE OF SUCH INFORMATION. THE USE OF ANY SUCH INFORMATION WILL BE ENTIRELY AT THE USER'S RISK.

Part number: 512-0088-01-01 Rev 1

Contact information:

Phone:	1-800-670-0707	(toll-free in North America)
--------	----------------	------------------------------

Fax: 1-604-420-2145 (outside North America)

Email: CustomerService@xantrex.com

Web: www.xantrex.com