

# ERRATUM

## A Toughened Epoxy Resin by Silica Nanoparticle Reinforcement

P. Rosso, L. Ye, K. Friedrich, S. Sprenger

[Article in J. Appl. Polym. Sci. 2006, 100, 1849]

When first published, Figures 4 and 5 were incorrect. The correct Figures 4 and 5 are shown below:




Figure 4. Fracture surfaces after crack opening of CT-samples; left: Araldite-F, right: nano SiO<sub>2</sub>-reinforced.




Figure 4. (continued from the previous page)




Figure 5. High magnification SEM at the crack tip zone.