



Contents lists available at ScienceDirect

Journal of Sound and Vibration

journal homepage: www.elsevier.com/locate/jsvi



Corrigendum/Erratum

Corrigendum/Erratum to: Aerodynamic sound production in low speed flow ducts [79 (2) (1981) 263–289]

P.A. Nelson, C.L. Morfey*

Institute of Sound and Vibration Research, University of Southampton, Southampton SO9 5NH, UK

Corrigendum: P.A. Nelson, C.L. Morfey, *J. Sound Vib.* **79** (1981) 263–289.

An error has occurred in the presentation of experimental data in Figs. 7, 9, and 10. The error can be corrected by subtracting 6 dB from the vertical scales; equivalently, the values of $K^2(St)$ presented in these figures should be divided by 4. The correction applies to all data presented in Figs. 7, 9, and 10.

Erratum: P.A. Nelson, C.L. Morfey, *J. Sound Vib.* **79** (1981) 263–289.

Page 279, Fig. 7: The figure caption as printed is truncated on the right-hand edge. The correct ending of each line is given below, with the missing text underlined:

(first line) and drag
(second line) (g) 0.1 m,

Also, in panel (g) of the figure, the inset diagram is wrongly labelled. Instead of 0.5 m it should read 0.05 m.

DOI of original article: [10.1016/0022-460X\(81\)90372-2](https://doi.org/10.1016/0022-460X(81)90372-2)

* Corresponding author.

E-mail address: clm@isvr.soton.ac.uk (C.L. Morfey).