Canon

MODEL: **GP605 / 555 / 605P**

SUBJECT: **Laser Checking Tool**

Details:

Please note that the part number for the Laser checking tool is incorrect in the current service manual/handbook.

The part number quoted is FY9-4013

This **should** be FY9-4008