![Keysight Technologies logo]

E4980A/E4980AL Precision LCR Meter Firmware Revision History

Rev. 20160318

Note:
The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Keysight representative.

Revision A.06.15   … Released Mar. 2016
1. For FW A.06.13
2. Fixed Turn ON error due to DSP response

Revision A.06.13   … Released Sep. 2015
1. For FW A.06.11
2. Fixed minor security hole in VxWorks

Revision A.06.12   … Released Sep. 2015
1. For FW A.06.10 or below
2. Fixed minor security hole in VxWorks

Revision A.06.11   … Released Apr. 2015
1. Initial for A.06.11
2. Support new LCD/FPGA

Revision A.06.10   … Released Apr. 2015
1. For FW A.05.00 or below
2. Support old LCD/FPGA

Revision A.05.00   … Released Nov. 2014
1. Support E4980AL option 102/052/032

Revision A.04.00   … Released Sep. 2014
1. Rebranding to Keysight

Revision A.03.00   … Released Jun. 2013
1. Added new options (Opt.030/050/100/200)
2. Fixed bug on entering "-" manually

Revision A.02.21   … Released Aug. 2011
1. Fixed bug on LAN Socket.

Revision A.02.21   … Released Aug. 2011
1. Fixed bug on LAN Socket.

Revision A.02.20 … Released Jul. 2009
1. Fixed bug on I/O error through device side USB control.

Note: For MY46204137 and above, the firmware revision 2.20 and later can only be installed. Do NOT attempt to install the older firmware revisions.

Revision A.02.13 … Released Nov. 2007
1. Fixed bug on signal output during Step Delay time in L-Rdc measurement mode (Opt 001).

Revision A.02.12 … Released Aug. 2007
1. Corrected DC Bias current setting resolution on Option 002 (40 A configuration).
2. Fixed bug on INDEX/EOM output at Open/Short/Load correction.
3. Fixed bug with INDEX/EOM output on Scanner Interface (Opt. 301).

Revision A.02.10 … Released Apr. 2007
1. Added function for selecting DC Bias Range (Auto On/Off).
2. Fixed open correction issue.

Revision A.02.00 … Released Nov. 2006
1. Added functions for LXI class C.
2. Fixed DNS server issue.
3. Fixed DHCP server issue.

Revision A.01.05 … Released Aug. 2006
1. Fixed OPE/SHORT correction issue.

Revision A.01.04 … Released Jul. 2006
1. Fixed LIST:STM:TYPE command issue.
2. Fixed recall function issue.

Revision A.01.03 … Released Jun. 2006
1. Added avoidance routine for "boot fail".

Revision A.01.02 … Released Jun. 2006
1. Changed DC bias list sweep sequence.
2. Changed OPC? Command specification.

Revision A.01.01 … Released Apr. 2006
1. Changed Handle I/F output specification when "Fixture cover open" message is displayed.

Revision A.01.00 … Released Mar. 2006
1. Initial Release.