E5072A ENA Network Analyzer Firmware Revision History

Rev. 20160630

Note:
The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Keysight representative.

Revision B.02.30   … Released June 2016
Add New ECal (N7554A, N7555A)

Revision B.02.20   … Released July 2015
Support Option-006 Wireless Power Transfer Analysis

Revision B.02.11   … Released July 2015
Changed Power On Test limits and Diag Test limits

Revision B.02.02   … Released April 2015
Bug Fixes. Analysis > Transform cannot be set to "ON"
          FW crash when Rotate Adapter soft key is pressed

Revision B.02.00   … Released December 2014
Rebranded to Keysight
Changed OS to Win-7

Revision A.01.14   … Released October 2014
Minor Enhancement.
Bug fixes.

Revision A.01.13   … Released March 2014
Bug fixes. Receiver Levelling doesn't work properly on Ch2 and above.

Revision A.01.11   … Released February 2014
Bug fixes. The previous reading of marker is output after format change. This occurs only when Display update is off.

Revision A.01.06   … Released February 2013
Fixed minor bugs.

Revision A.01.03   … Released June 2012
Fixed minor bugs on system recovery issues.

Revision A.01.03   … Released October 2011

Fixed minor bugs.

Revision A.01.00   … Released June 2011
Initial revision