SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-D2010 **No.** 139

Subject: Part Number Correction - T901 Transformer **Date:** October 25, 1990

Symptom:
(**)

The part number listed on page 62 of the service manual for Reference Number T901, Transformer Power, is incorrect.

Solution: Please note the correct part number shown below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
T901	Transformer, 5V Supply	1-449-611-11	1-448-517-21



Receiver

CSA-13

PRINTED IN U.S.A.
CSA-131090-5