SONY

Hi-Fi Products

Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive Park Ridge New Jersey 07656

Model: TA-AX311

No. 235

Subject: Incorrect Part Number: D957

Date: January 20, 1992

Symptom:
(**) The schematic diagram indicates a type UZL-27 for D957 and the parts list description indicates a type HZS30-1L.

Solution: The correct component type to be used as replacement for D957 is shown below:

REFERENCE	DESCRIPTION	PART NUMBER
D957	UZL-27H	8-719-002-48

[AMP-R BOARD]



Reference: FPR-M2977

PRINTED IN U.S.A.
CSA-13192-1