**SONY**

Hi-Fi Products

# Service Bulletin

**Sony Service Company** Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

**Model:** **STR-D2020** **No.** 268

**Subject:** Unit Getting Hot, then Goes Into Protect **Date:** May 29, 1992

**Symptom:**
**(12)** Unit gets very hot, then goes into protect.

**Solution:** Short the power supply ground to the audio ground as shown below:




**[MAIN POWER BOARD]**




Reference: FPR-N0717

PRINTED IN U.S.A.
CSA-13592-3