(Release May 1, 2001)

New features and changes since version 1a

1. The procedures have been enhanced to support System Two Cascade.
2. Support has been added for three new DVD discs.
3. Support has been added for 96 kHz sample rate.
4. Procedure code now provides better support for external sweeps:
5. Sweeps start to allow data collection even when the start value is not satisfied.
6. Sweeps stop (time out) even when the end value is not satisfied.

How to Run the CD & DVD Test Procedures

1. Run the accompanying Setup file located on the CD to install the required files into a new folder in your APWIN directory.
2. Refer to Application Note 1A for specific information regarding APWIN configuration and connection considerations.
3. Set the working directory (Click File > Set Working Directory) to specify the new directory defined in Step 1.
4. Individual procedures are supplied for each measurement or you can run a menu that allows you to select which tests to run. To run the main menu, open and run the CDTEST.apb procedure:

   A. Click File > Open > Procedure
   B. Choose CDTEST.apb
   C. Select RUN under the Procedure menu Refer to Application Note 1A for information on the individual tests.

Note: This application will not run correctly with APWIN in Demo Mode.