Canon

Service Information

Model : **Network Printer Board-F1**
Network Multi PDL Printer Board-H1
Network Printer Board-K1

Ref. No. : FF-T01-V1-000093-01
(00-OIPD0-B0059)

Date : June 5, 2000

Approved by :

© Canon (UK) Limited

Location : HARD DISK DRIVER UNIT

Subject : PARTS NUMBER CHANGE WITH HARD DISK CAPACITY CHANGE

Reason :
The hard disk capacity of Network Printer Board-F1/K1 and Network Multi PDL Printer Board-H1 will be changed from 2.1 GB to 6 GB.

Service Parts :

No.		Description	Part number	Q'ty	Stock	Inter-change-ability	EFI P/N
1	Old	HARD DISK DRIVE UNIT	FE1-5020-000	1→0	C	Yes Yes	
	New	HARD DISK DRIVE UNIT	FE1-5020-010	0→1	D		45015535

Affected Machine :
It is switched from the production in and after June 2000.
(1) Network Printer Board-F1
With this change, the product orders are changed as follows.

     F61-7403-030   Network Printer Board-F1, USA
     F61-7403-720   Network Printer Board-F1, AMS/UK
     F61-7403-722   Network Printer Board-F1, FRN
     F61-7403-724   Network Printer Board-F1, GER
     F61-7403-726   Network Printer Board-F1, ITA

The hard disk change is synchronized with the change of memory amount reported in "FF-T01-V1-000092-01".

(2) Network Multi PDL Printer Board-H1 / Network Printer Board-K1
For 3 months from the shipment in June, red stickers are applied on the shipping cartons.

Remarks :
Although the hard disk units are 6 GB, due to the restrictions on Operating System of Network Printer Board-F1/H1/K1, the capacity that can be recognized and used is "4 GB".
The User Manual describes that the available capacity is "4 GB".