⑫ Click "Finish" to close the Wizard.

The FieldMaxII installation requires the Found New Hardware Wizard to run twice—the following step is the beginning of the second Wizard cycle.

⑬ When the Found New Hardware Wizard appears, select "No, not at this time" and then click "Next."

⑭ Click "Next" to automatically install the software.

⑮ Click "Next" to complete the installation.

If this FieldMaxII is connected to a new USB port, or an additional FieldMax II is connected, the Found New Hardware Wizard will activate and must be completed again.

Contact Information

USA	
Phone:	1.800.343.4912
Fax:	971.327.2777
E-Mail:	info_service@Coherent.com
Europe	
Phone:	+49-6071-968-0
Fax:	+49-6071-968-499
E-Mail:	info_service@Coherent.com
International	
Phone:	971.327.2700
Fax:	971.327.2777
E-Mail:	info_service@Coherent.com

For the latest Customer Service information, refer to our website: www.Coherent.com.

Quick Start Guide

FieldMaxII™ *Software Installation*

(FieldMaxII-TOP, -TO, and -P)

This guide explains how to install the FieldMaxII™ software. For detailed information about the FieldMaxII, refer to the user manual that shipped with the meter.

⚠ **Do not connect the FieldMaxII to the USB PC port at this time. The software must be installed *before* physically connecting the meter to the computer.**

Software Installation

❶ Insert the FieldMaxII CD into your CD-ROM drive. If Autorun is enabled on your system, installation will start automatically; otherwise, select Run from the Start menu and then type **D:\Setup.exe** (substitute the appropriate letter of your CD-ROM drive for **D**).

❷ Click "Next" on the Welcome screen.

❸ Read the License Agreement. Select "I accept the license agreement" and then click "Next."

❹ Fill in your name and organization. Select "Only for me (your name)" and click "Next."

❺ Select the default destination folder by clicking "Next."

❻ Click "Next" to automatically install the LabVIEW® drivers and create a FieldMaxII desktop icon.

❼ Click "Continue Anyway."

❽ Click "Finish" to complete the software installation and view the README file.

⚠ **Connect the FieldMaxII to the USB PC port before continuing with this installation.**

❾ When the Found New Hardware Wizard appears, select "No, not at this time" and then click "Next."

❿ Click "Next" to automatically install the software.

⓫ Click "Continue Anyway."