HP 10s Firmware Release

Release Date: 2012-11-29
Version information: Rev. 16851

The newest revision of the firmware, 2012-11-29 (final testing still underway), contains several fixes/improvements. No product documentation changes are required as these changes either bring the behavior back in line with what is described in the manual, or are such extreme cases that they were never intended for user knowledge but rather just as defensive limits to prevent the user from doing something incorrect or that would drain battery life.

Start Menu Shortcut

When the 10s emulator is installed, it titles the calculator .exe file with 300s instead of 10s.

No other known issues exist at this time.