Important Notice

Regulatory Markings, Safety, and EMC Compliance

The information in this addendum is provided to improve the contents of the affected Keysight 82357B product manuals pertaining to the regulatory markings, safety, and EMC compliance updates.

C-Tick logo has been replaced with the RCM logo

The C-Tick logo is replaced with the RCM logo.

Table 1   C-Tick logo and RCM logo

C-Tick logo	RCM logo	Description
N10149		The RCM mark is a registered trademark of the Spectrum Management Agency of Australia. This signifies compliance with the Australia EMC Framework regulations under the terms of the Radio Communication Act of 1992.

Updated safety compliance

– IEC 61010-1:2010/EN 61010-1:2010
– USA: ANSI/UL Std. No. 61010-1:2012
– Canada: CAN/CSA C22.2 No. 61010-1-12

Updated EMC compliance

– IEC 61326-1:2012/EN 61326-1:2013
– CISPR 11:2009/EN55011:2009
– CANADA: ICES/NMB-001: Issue 4, June 2006
– Australia/New Zealand: AS/NZS CISPR 11:2011

KEYSIGHT
TECHNOLOGIES

Affected Keysight 82357B product manuals

The following lists the affected product models and the respective manuals.

– Keysight 82357B USB/GPIB Interface User's Guide
– Keysight 82357B USB/GPIB Interface Quick Start Guide

KEYSIGHT
TECHNOLOGIES