KEYSIGHT TECHNOLOGIES

E5061B Network Analyzer Firmware Software Revision History

Rev. 20160630

Note:
The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Keysight representative.

Revision B.04.80 … Released June 2016
1. Supported new ECal (N7554A, N7555A)

Revision B.04.50 … Released May 2016
1. Supported new touch screen driver

Revision B.04.10 … Released July 2015
1. Supports Option-006 Wireless Power Transfer Analysis

Revision B.04.00 … Released October 2014
1. Rebranding from Agilent to Keysight
2. Enhanced the licensing management

Revision B.03.03 … Released July 2014
1. Bug Fix: LAN connection failure with Telnet/Socket.

Revision B.03.02 … Released July 2014
1. Initial version of Windows 7.

Revision A.02.22 … Released December 2013
1. Bug fixes. The previous reading of marker is output after format change. This occurs only when Display update is turned off.
2. The query of :SENSe:CORRection:COLLect:ECAL:INFormation? is not the same as the E5071C.

Revision A.02.21 … Released August 2013
1. Minor Enhancement
2. Bug Fix

Revision A.02.12 … Released October 2012
1. Bug Fix

Revision A.02.11 … Released August 2012
1. Fixed bugs related to firmware boot up

Revision A.02.09 … Released June 2012
1. Fixed minor bugs on system recovery issues

Revision A.02.06 … Released October 2011
1. Added the system error correction ON/OFF capability

Revision A.02.04 … Released May 2011
1. Added Touch Panel Driver check functions
2. Enhanced Firmware Revision dialog design

Revision A.02.00 … Released Jan 2011
1. Added RF NA options
2. Added Impedance analysis option for LF-RF NA
3. The return values of VBA query commands on instrument setting has been changed from full spelling to abbreviation for compatibility with other ENA series products.
   e.g. LINear -> LIN, PHASe -> PHAS

Revision A.01.14 … Released Jun 2010
1. Improved of overload protection function
2. Fixed a bug related to the system exit function

Revision A.01.12 … Released Apr 2010
1. Fixed a bug related to internal ranging operation

Revision A.01.10 … Released Dec 2009
1. Customer first release

Revision A.09.41 … Released Sep 2009
1. Demo use only