11760S-01A

HP 11760S Power Sensor Calibration System

Serial Numbers:
0000A00000 / 9999Z99999

Y2K update information
The HP 11760S is out of support life in November of 1999.
While the HP 11760S is compliant when running as a standalone
system, the network operating system (SRM/UX or BASIC) may
need a patch if running in a server/client environment. There
is also a PC based compliant alternative.

Situation:
The HP 11760S Power Sensor Calibration System is compliant
operating as a standalone system or on a network as long as
the underlying operating system is compliant.

HP has partnered with Intercal, a developer of calibration
software, to provide a PC based, compliant version of the 11760S.

Solution / Action:
Contact TAMS Test and Measurement Systems Inc. at www.tamsinc.com
for information and products to upgrade your SRM/UX or BASIC
system.

Contact Intercal through their website at http://intercalinc.com/
for more information on their PC based calibration system.

Date:
08 April 1999

```
******************************************************************
*                                                                *
*                      INFORMATION ONLY                          *
*                      ----------------                          *
*                                                                *
*    AUTHOR/ENTITY: _TE / 5340_____  *
*  ADDITIONAL INFO: _____  *
*                                                                *
******************************************************************
```