S E R V I C E   N O T E

SUPERSEDES: 85620A-02

85620A Mass Memory Module

Serial Numbers: 0000A00000 / 3003A01967

Firmware Upgrade Kit, Part Number 85620-60013

To Be Performed By: Agilent-Qualified Personnel or Customer

Continued

DATE: August 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	**AGREEABLE TIME**	■ PERFORMANCE ENHANCEMENT ☐ SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE ■ ON-SITE ■ SERVICE CENTER	AVAILABLE UNTIL: August 1995
AUTHOR: GPB	ENTITY: 5300	ADDITIONAL INFORMATION:

·:·:· Agilent Technologies

Parts Required:

Table 1: ROM Upgrade Kit 85620-60013

Quantity	Description	Part Number
1	EEPROM, Programmed U1	85620-80023
1	EEPROM, Programmed U2	85620-80024
1	EEPROM, Programmed U3	85620-80025
1	Label, "Rev. B"	85620-80003
1	Installation Note	85620-90023

Table 2: 85620A Firmware Revisions and ROM Part Numbers

Firmware Date Code	ROM Part Number 85620-		
	U1	**U2**	**U3**
890214(A)	80005	80007	80009
890524(B)	80014	80015	80016
910116(C)	80023	80024	80025

Situation:
Later versions of instrument firmware are sometimes implemented to improve instrument performance and reliability.

Solution/Action:
A firmware upgrade kit, part number 85620-60013, has been set up for the 85620A Mass Memory Module. The kit contains the latest revision of instrument firmware, a revision label to be affixed to the module cover, and an installation note. Table 1 gives the contents of the latest revision in the kit. Table 2 shows the part numbers of the EEPROMs for each revision. The date code is displayed in the form YYMMDD.