37717A-17

37717A PDH/SDH BER Test Set

Serial Numbers: 000000000/999999999

Y2K Update Information

Compliance Status:
Y2K Compliant.

Duplicate Service Notes:
37714A-13
37717B-21
37717C-14
37778A-01

Firmware Configuration:
There are two formats of firmware revision code, one is a 4 digit code the other takes the form A.XX.XX.

All revisions above 3925 and at or above A.03.17 except for A.03.35 and A.03.99 are fully compliant. Earlier revisions exhibit a date anomaly see comments.

Additional Comments:
Some earlier versions of the product as stated in Firmware Configuration have a date anomaly when used in Stored Measurement Graphics mode. At the end of every leap year (on 31st December) the date will be shown incorrectly as 1st January. On 1st January the date will be correct (1st January). THIS IS SELF CORRECTING NO USER INTERACTION IS REQUIRED.

While this condition is self correcting and exists only for 1 day some customers may wish have this anomaly corrected. These customers should contact their local Agilent representative to arrange a return to factory upgrade.

Date: January 2000

```
*************************************************************
*                      INFORMATION ONLY                     *
*                                                           *
*  AUTHOR/ENTITY: ___BM/E610_________________________________ *
* ADDITIONAL INFO: _________________________________________ *
*************************************************************
```