S E R V I C E   N O T E

SUPERSEDES: NONE

37722A Digital Telecom Analyzer

Serial Numbers: 0000U00000 / 9999U99999

Display flicker not a fault when used in graph storage mode

Duplicate Service Notes:
37701A-09
37702A-03
37704A-03
37717A-07
37717B-04
37721A-13
37722A-03
37724A-07
37732A-06

Situation:
Some instruments appear to flicker when used in the graph storage mode, independent of storage resolution. When the measurement start the pattern on the display changes to indicate both the start of gating and start of storage. This display may flicker. This is not a fault. DO NOT CHANGE THE DISPLAY!

Replacing the display **WILL NOT** fix the anomaly.

DATE: October 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GS	1400	

Agilent Technologies